



3.10.5 Individual Plate Defect Locations



Legend:

- => 50% Wall Loss
- 40-49% Wall Loss
- 30-39% Wall Loss
- 20-29% Wall Loss
- Patch or Strike Plate
- Weld Defect
- Pit

Tank Ø = 14.6m  
 Floor Plate Nominal Thickness: 6.4mm  
 Annular Plate Nominal Thickness: 8.0mm

Comments: 1: All figures are in millimetres

Drawing by:	Drawing Date:	Inspection date:
Client:	Desc: Plate 3	Report #:

